



**MAKING YOUR WORLD A SAFER PLACE**

## Miller Edge Discontinues LC-K36, LC-K72

**Effective immediately**, the LC-K36, LC-K72 have been discontinued. For any LC product in the field still under warranty, the replacement products will still be available up until the warranty expires. For applications where you would have used the LC-K36, LC-K72, Miller Edge recommends our newest non-monitored light curtain: RLC-K36, RLC-K72.

Save BIG with the Relay Light Curtain in both time and money with significantly lower pricing than the LC and easier installation. Rest assured that the RLC has the same proven reliability as our trusted MLC line.

### RLC Features:

- 50' lead wire, no junction boxes necessary.
- Normally Open, and Normally closed output
- Fail-safe, signals with loss of power
- Cost-Effective and easy to install



800-220-3343

